





FEEDER OF HAMMER MILL

GBS

It consist of 2-4 pcs screw conveyors coupled working. Product dose went to hammer mill is arranged by motor driver placed at bottom. Product going down from screw conveyor to feeding bunker is got into hammer mill by bottom gates.



MODEL	DIMENSIONS					MOTOR POWER	MOTOR QTY	SCREW CONVEYOR QTY	HAMMER MILL
	A	B	C	D	E				
GBS 400	1200	700	1100	650	280		1	2	DG Ø540x380 DG Ø650x450 DG Ø1130x400
GBS 600	1300	1000	1170	600			1	2	DG Ø1130x600
GBS 700	1390	1040	1240	475	600	2,2 Kw	1	2	DG Ø1130x700
GBS 800	1450	1200	1260	475	700	2,2 Kw	1	2	DG Ø1130x800
GBS 1000	1600	1870	1300	785	1135	1,5 Kw	2	4	DG Ø1130x1000
GBS 1200	1600	2120	1350	800	1350	2,2 Kw	2	4	DG Ø1130x1200

GPS-ASCOM